

TABLE OF CONTENTS

Section 1 – Goals	1
Section 2 – Organization	1
Section 3 – Overflow Emergency Response Plan	3
Section 4 – Fats, Oils, and Grease (FOG) Control Program	9
Section 5 – Legal Authority	10
Section 6 – Measure and Activities	11
a. Collection System Map	11
b. Resources and Budget	12
c. Prioritized Preventive Maintenance	12
d. Scheduled Inspections and Condition Assessment	13
e. Contingency Equipment and Replacement Inventories	14
f. Training	15
g. Outreach to Plumbers and Building Contractors	16
Section 7 – Design and Construction Standards	16
a. Standards for Installation, Rehabilitation, and Repair	16
b. Standards for Inspection and Testing of New and Rehabilitated Facilities	16
Section 8 – Capacity Management	16
a. Capacity Assessment	16
b. System Evaluation and Capacity Assurance Plan	17
Section 9 – Monitoring, Measurement, and Program Modifications	17
APPENDIX A	20
APPENDIX B	23
APPENDIX C	29

not perform maintenance on the lateral.

Property owners own the lateral from the connection at the structure to the main line. Tree root intrusion, grease buildup, cracks, breaks, etc., are all the responsibility of the property owner. Maintenance of the lateral is the property owner's responsibility; however, the City will accept maintenance responsibility for laterals from the cleanout adjacent to the property line to the main line as described above.

